


Care Instructions

- For PUR-lightweight coatings -

Imitation leather with textile carrier and a PUR-coating for protective workwear, clothing materials and imitation leather for upholstery



Wash cold at 30 °C
by using a mild detergent.



Gentle drying is allowed
up to 60 °C.



Bleaching is not allowed.



No dry cleaning.



Do not iron.

Further Indications

- In case of light stains, wipe the surface with a pH-neutral soap solution and a soft cloth.
- Do not clean with organic solvents (alcohols), aggressive soaps or abrasive cleaners. Disinfection only with disinfectants recommended by us (list available on request).
- No special care for material preservation necessary.
- The listed indications are not a guarantee and do not release the user from his duty of care when handling materials and cleaning agents.