

Storage Instructions

Label according to VDA

- For PVC and PUR coated products and foils -

- Before using, the material should be stored for 24 hours at ambient temperature, in order to avoid differences in warming and to guarantee steady process parameters. (Preferably, the material is stored at processing conditions.)
- Storage areas with high humidity as well as external bearing should be avoided. The rolls may not be exposed to liquids, chemicals, disinfectants or detergents. The use of diesel forklift trucks in the warehouse should be avoided.
- The storage in an enclosed space with 20 80% humidity and 20°C +/- 10°C, must not exceed 24 months.
- The delivered material must be protected from direct sunlight.
- Any kind of pressure or contact with hard, sharp-edged or peaked objects must be avoided.
- It is essential for storage that the product can clearly be identified by the label
- Explanations of the different details shown on our label can be found in the figure below.
- The FIFO-principle (First In First Out) must be observed.

When processing an object only material from one production batch should be used.

